


SeaQuest Status

July 21-27, 2014


Brian Tice

July 28, 2014


SeaQuest Integrated Protons
3/31/14 - 7/26/14




SeaQuest Integrated Protons
7/21/14 - 7/26/14





SeaQuest Integrated Protons
3/31/14 - 7/26/14



SeaQuest Integrated Protons
7/21/14 - 7/26/14



We have the data from night of 7/26 to present. Data upload script had paused. Has been fixed/restarted. Expect same levels of live time.



Detector Status - All systems performing well

- Temperature, humidity, pressure NM4 environment added to datastream
 - Allows us to correlate noisy channels, leak currents, etc with environmental conditions
- **We were not affected by the Saturday night power glitch**
 - Flickering light may have scared shifters

Beam Updates

Ready for 4 turns, Ready to test 45s cycle

- Neutral density filter in beamline Cerenkov monitor filtering more light
 - 25% NDF was replaced with 10% -> Protects from saturation effects.
- Our redundant duty factor measurement using hodoscopes was changed to use lower rate paddles, also protecting from saturation
- **SeaQuest would like turn13=4 to be new standard beam condition**
 - Results of survey of MI52 will show if this condition is OK for beams
 - (this was said last week as well)

- 45s cycle – ready for tests. Target and DAQ experts would like the be present.
- **Advanced notice of this test would be greatly appreciated**

Target Updates

Issues with pressure readout, table motion

- H2 Pressure Readout
 - **Attempt to replace H2 supply pressure sensor went awry**
 - Electronically disconnecting sensor caused system to read high pressure, **vent some H2**
 - Sensor was immediately reconnected
 - Took data on other targets until H2 could be refilled (completed Saturday evening)
 - Replaced a bad silicon control rectifier to maintain stable pressure
 - Target motor controller was dead after this replacement. Installed spare.
 - **Refill and recool of H2 went smoothly. Resumed taking H2 data.**
- Target table motion
 - We were **unable to reliably move target after the SCR and target motor replacement**
 - Behavior consistent with **noise on target position encoder** line
 - Removed an LED encoder position display
 - Improved ground in target area
 - **Target motion now good.** Has been increasingly reliable after this fix
 - Looking to purchase new/spare target encoder

Other Updates

- VESDA electronics moved from East to West side of NM4
 - West side of this part of NM3 has much lower rad levels
 - Expect fewer malfunctions (false positives)
- Glycol/water from last week's magnet drip surveyed and removed from NM4
 - Recall: Magnet cooling line supply side hose cracked was reported at previous AEM
- NIM coincidence unit died and was replaced by spare. This is not critical logic.
- Measured NM3 rad levels in candidate locations of UNSER monitor electronics

Backup

Turn 13=4 test

- Expected to increase beam intensity by $\sim 1/3$ compared to our nominal three-turn injection
- Wednesday afternoon, we received an hour of beam using four-turn injection into booster.
- G2Sem $\approx 6.3E12$ ppp (vs. typical $4.8E12$ ppp). *SeaQuest design: $1E13$.*
- Accepted triggers/spill increased by $\approx 25\%$
- SeaQuest hodoscopes and drift chambers show no reduction in efficiency.
- Onset of saturation in Cherenkov monitor visible in Cherenkov-sum/G2SEM. Adjusting PMT attenuation this week.

**SeaQuest would like this as new nominal running.
Waiting to hear about radiation impact on MI52.**

