




AEM SeaQuest


Paul E Reimer
25 April 2016

Protons



ing name here; then, click "Apply to All"

Cooling Water Temperature



DAQ

- Sunday Afternoon:
 - Accepted trigger rate dropped gradually by 1/3
 - Noise noticed in one chamber causing additional dead time (possible red herring?)
- Sunday Evening:
 - No triggers being accepted by DAQ
- Faults found so far:
 - Bad NIM fan out--replaced
 - 3 ROC not working
 - Two appear to be bad CPU boards—fixed as we talk
 - One possible TDC or Trigger problem

- Experts tired, but working on it.

