

SeaQuest Status:

- Outages last week for booster cavity replacement and quad ground fault.
- Two SeaQuest issues:
 - Large leakage current in station I drift chamber addressed during booster replacement. Two offending wires located and disconnected.
 - Target position occasionally read out-of-position for tungsten position. Traced to slow control readout problem.
- New Station I drift chamber undergoing HV training in Lab 6 (@ I 300 of 2000V). Will be moved to NM4 in ≈ 3 weeks.

New SI drift chamber undergoing HV training



Production data taking

Last week

